

## IMMO

<b>Brand, model</b>			<b>Type of work</b>
mazda 2	dash 93c66	ecu sid206 95320	sync vin replacement
mazda2, 3	dash 93c66	ecu 93c56	sync, vin replacement
mazda 3	dash 93c56	ecu EDC16 95160	sync, vin replacement
mazda 3, 5	dash 93c56	ecu 93c56	sync
mazda 3 5	dash 93c56	ecu 24c02	sync
mazda 6	dash 93c66	ecu 93c86	sync
mazda 626	immo 3D33J	ecu EEC-V 95040	sync
<b>FORD - focus, C MAX, fiesta, figo, fushion,torneo, transit connect, Mondeo.</b>	ecu sim28 93c86	dash 9s12h256	sync
	ecu ESU-121,ESU-131. 95040	dash 9s12h256	sync
	ecu sid206 95320	dash 9s12h256	sync vin replacement
	ecu EDC16 95160	dash 1K78X	sync vin replacement
	ecu sid803 95320	dash 1M80F	sync vin replacement
	ecu sid804 93c56	dash 24c16	sync
	ecu sid804 93c56	dash 24c08	sync
	ecu sid202 95320	dash 9s12h256	sync vin replacement
	ecu sim210 93c86	dash 24c08	sync
	ecu sid802 93c56	dash 24c08	sync
	ecu sim21 93c86	dash 9s12h256	sync
	ecu sid206 95320	BCM 25LC320	sync vin replacement
ford kuga	DCM3.5 95640 SID206 95320	RFA ms9s12XDT384	sync vin replacement
ford fiesta 2010+	ecu Bosch ME17.2 EMS 2211, 2205.	dash mc9s12xeg384	sync vin replacement, manual key entry.
Ford Focus3, Escape.	ecu EMS 2204	BCM 95320	sync
	ecu (MEDG17)	BCM 95320	sync
	ecu (MEDG17)	BCM(MC9S12XEP768)	sync
ford tranzit	ecu SID208 tricore TC1797	BCM(MC9S12dp512)	sync vin replacement, manual key entry
Mondeo MK4 2010+	ecu SID 807 EVO tricore 1797 ESU-412 95040, DCM 3.5 95320	BCM 7G9T-14A073. DELPHI 25LC320 BCM BG0T-14A073-EL R6F64525	sync,vin replacement, ABS replacement
S-MAX	ECU-DELPHI3.5 95320, SID807EVO.	BCM BG9T-14073-BL R5F64525	sync,vin replacement, ABS replacement
Nissan almera clasic	dash 93c66	ecu MH7055	sync
Nissan Micra, Tiida K12	ikey 93c56	ecu 93c66	sync, manual key entry 4D
	BCM 95080	ecu 93c66	sync, manual key entry pcf7936, PIN.
<b>Renault - megan3, fluence3, scenic3</b>	ecu 95640	BCM (nec PD70F3384)	sync
Renault master3.	ecu EDC17c11	BCM (70F3375)	sync
Renault duster	ecu 95640	UCH 93c66	sync
Renault Megan 2	ecu sagem S3000	UCH MC9S12DT256 3L91N	sync

<b>P2-VOLVO V70, S60, S80, XC70, XC90 CEM-L &amp; CEM-H 00005XXXXXX+</b>	Bosch EDC16 95320 Bosch EDC15 95P08 Bosch ME7 95080. Denso 93c56. Denso 93c86	CEM 93LC86	sync, manual key entry, +remote control key fob configuration replacement.
<b>P2-CEM-L &amp; CEM-H 00004XXXXXX Volvo s60 xc70 xc90</b>	ecm 93c56, 95080, 95P08.	cem M32C +93LC86	sync, manual key entry, +remote control key fob configuration replacement.
<b>P3-CEM s80 xc60</b>	DENSO- R5F72546R	cem R32C r5f64525	sync, conguration replacement, ABS replacement manual key entry in CEM and KVM.
<b>P3-CEM 7G9T- 14C256-Volvo s80, V70, XC60, XC70</b>	ecm 95080, 95640, SID206 95320, EDC17 TC1796, Denso 93A86.	renesas (M32C) M30882FJ 25LC320	sync, conguration replacement. ABS replacement + slc 95040 manual key entry
<b>P3-CEM BG9T- 14C256 V60, XC60</b>	EDC17cp22 tc1796, Denso 93A86.	cem R32C r5f64524kfd	sync, conguration replacement, ABS replacement manual key entry in CEM and KVM.
<b>P1- C30,S40,V50,S60- D4.</b>	ecm SID807EVO tricore 1797, EDC17cp22 tricore-tc1796	cem (1M84E)	sync, conguration replacement, ABS replacement manual key entry
<b>P3-V40 D2 2013+</b>	ECM SID807EVO tricore 1797, MED17.2 tricore tc1767. DENSO-R5F72546R	cem (31394621) SPC560B60L7X, st95320.	sync, conguration replacement, ABS replacement manual key entry in CEM and KVM.
<b>P1-Volvo – C30, V50, S40, V40, C70.</b>	ecm EDC16 95160	cem1L15Y	sync, + scl 95040, conguration replacement. manual key entry+remote control key fob
	ecm denso 95080	cem 1K79X	sync,+ slc 95040, configuration replacement manual key entry+remote control key fob
	ecm sid803,sid206 95320	cem(9s12)	sync,+ slc 95040, configuration replacement manual key entry+remote control key fob
	ecm sim280 93c86	cem (9s12)	sync,+ slc 95040, configuration replacement manual key entry+remote control key fob
	ecm denso 93c56	cem (9s12)	sync,+ slc 95040, configuration replacement manual key entry+remote control key fob
	ecm ESU 121,131,411, 95040	cem (1k79x)	sync,+ slc 95040, configuration replacement manual key entry+remote control key fob
	ecm ME9 95080	cem1L15Y	sync,+ slc 95040, configuration replacement manual key entry+remote control key fob \
<b>Volvo – s80, s60, v70, xc90.</b>	ecm denso 93c56	cem 28f400	sync, manual key entry, remote control key fob configuration

			replacement. recovery of damaged by incorrect reading of dump 28f400
	ecm95p08 EDC15C11	cem 28f400 diesel	sync, manual key entry, remote control key fob configuration replacement. recovery of damaged by incorrect reading of dump 28f400
	ecm 95p08	cem 28f400 petrol	sync, manual key entry, remote control key fob configuration replacement. recovery of damaged by incorrect reading of dump 28f400
	ecm 24c04	cem 28f400	sync, manual key entry, remote control key fob configuration replacement. recovery of damaged by incorrect reading of dump 28f400
<b>Volvo – s40, v40, s70, c70.</b>	ecm siemens 29f200	immo3 93c56, 93c66	sync
	ecm msa15.8 24c04	immo3 93c66	sync
	ecm me7.1.1 95p08	immo3 93c66	sync
	ecm msa15.5 24c02	immo3 93c66	sync
	ecm denso 93c56	immo3 93c66	sync
CEM P1,P2,P3.	P1-9s12ddt256. P2-28F400, renesas M32C. P3- renesas M32C, R32C, SPC560B60L7X.		configuration replacement
reconfiguration of VOLVO cars of all platforms from 1998 to 2015 of release.	activate cruise control - activate the adjustable speed limiter (Speed Limiter) - activate the on-board computer - activate fog lights (even where they are not provided) - install the DSTC system - activate the electric heater radiator - activate BLIS blind spot cameras - activate rain sensor - activate the heating of the rear sofa - activate the regular subwoofer - activate regular rotary xenon - activate the standard pre-heater - activate pre-heater timers - activate the correct operation of the rear LED lights VOLVO XC90 - activate the DRL function on regular PTF - activate the standard function of the autostart engine (gasoline) or pre-heater (diesel) from 2013 model year - activate parking sensors - activate the reception of radio stations of all frequencies - (de) activate the FOUR-C system - (de) activate automatic locking of locks at the beginning of movement - (de) activate step-by-step unlocking of doors		

	- (de) activate double lock of door locks - activate child locks - activate folding rear head restraints - activate (separate) climate control instead of air conditioning		
Volvo-SPA 2015+xc90, xc60, xc40, V90	CEM MPC5646G	ECM-Denso R5F72546R	sync.
CEM:MPC5748G CEM:MPC5646G	shutdown start-stop; activation of adaptive cruise, Pilot Assist; unlock video in motion; navigation; recognition of road signs; speed limiter - limiter (manual); automatic speed limiter (by signs); removal of the speed limit of 180 km/h for vehicles from 2020 onwards; Android Auto and Apple CarPlay; Polestar; disabling the steering column lock (a signature disease of age-related cars); Pilot Assist 3 (adjustment of speed in turns on navigation); activation of additional installed standard options - subwoofer, B&W, PTF, paddle shifters, parking sensors, cameras, etc.		configuration replacement
SCL OFF	P1, P3. SPA/CMA		
Disabling MOST Security ITP OFF	P1, P2, P3.		
<b>Chery geely, great wall, zoty, haima.</b>	immo m11-3600020 24c02	ecu ME 7.9.7 95080	restore dump immo and sync.+pin
	immo m11 24c02	ecu Delphi mt 22.1	restore dump immo and sync.+pin
	immo m11 24c02	ecu M.M. IAW 5SF4	restore dump immo and sync.+pin
	immo m12 24c02	ecu me797 95080	restore dump immo and sync.+pin
	immo 0L72A	ecu me797 95080	restore dump immo and sync.+pin
geely emgrand ec7	immo 93c56	ecu MT80	restore dump immo and sync.+pin+manual key entry
geely emgrand ec7	immo 93c56	ecu me7.8 95080	restore dump immo + sync.+pin+manual key entry
Chery Tiggo 5	T21 24c02	ecu me17.8.8 tc1728eprom	restore dump immo and sync.+pin
Chery Tiggo 5	smartbox 95160	ecu me17.8.8 tc1728eprom	restore dump immo and sync.+pin
Lifan mywey	BCM 9s12	ecu me17.8.8 tc1728eprom	restore dump immo and sync.+pin
Lifan celliya, x50, x60	immo 95040	ecu me 7.8.8 95080, ecu MT22.5	restore dump immo and sync.+pin manual key entry 4D.
Lifan Solano-2	PEPS-9s12g128	ecu-MT-22.5	sync,+pin
Toyota aygo	immo 24c04	ecu 95040	sync, manual key entry
Toyota duet	immo 93c66	ecu 93c56	sync, manual key entry
Toyota avensis	immo HC05	ecu 24c02, 93c56.	sync, manual key entry
Toyota Passo	immo 93c66	ecu RA57	sync, manual key entry, immo off
Toyota Verso	immo 93lc66	ecu 93c56	sync
<b>Daihatsu move,sirion</b>	immo 93c66	ecu 93c56	sync, manual key entry
daihatsu terios,boon	immo 93c66	ecu denso 93c56	sync, manual key entry

Subaru Forester XV,SJ.	Body 24c02	ecu 93c56	Dash 93c76 or 93c86.		sync
Subary Impreza	Body 24c02	ecu 93c86	Dash 93c86		sync
<b>Subaru impreza</b>	BCM 24c01	ecu hitachi 93c66			sync
<b>Subaru justy</b>	immo 24c08	ecu 24c04			sync
<b>Iveco daili</b>	bsi 95320	ecu EDC16 95640			sync
	immo 93c56	ecu EDC16 95640			sync
Suzuki ignes	immo x24c01	ecu 24c04, denso 93c56			sync, manual key entry
Suzuki liana, alto.	immo 93c66	ecu 93c56			sync, manual key entry
Suzuki samurai swift	immo 93c66	ecu 93c56			sync, manual key entry
Suzuki jimny	immo x24c01	ecu 93c56			sync, manual key entry
Suzuki wagon R	immo 93c56, TMS 370	ecu 93c56			sync, manual key entry
Suzuki bolena	immo 93c66	ecu 97101, 93c56			sync, manual key entry
Suzuki grand vitara	immo 93c66	ecu 24c04			sync, manual key entry
	immo 93c66	ecu 2.5l 93c66			sync, manual key entry
	immo 24c01	ecu 2.5l 93c66			sync, manual key entry
	immo 24c01	ecu EDC16 1,9D 95160			sync manual key entry
	immo x24c01	ecu 93c56			sync, manual key entry
	immo x24c01	ecu 93c46			sync, manual key entry
	immo x24c01	ecu 24c04			sync, manual key entry
<b>Suzuki</b> grand vitara 2.0 hdi EDC15C2 0281010559 1 Plug	immo 95020	ecu 95p08 + flash 29F400			working couple.
<b>Suzuki swift, splash.</b>	ecu 33910-73ku 93c66				manual key entry
Mitsubishi galant 9	immo 93c67	ecu 24c08			sync
Mitsubishi lancer 9	immo x24c01	ecu 8305f			manual key entry, immo off.
Mitsubishi space star, charisma.	immo 93c56	ecu 7203fa, 8200f			sync, immo off.
Mitsubishi lancer 10	kos 24c16	ecu 93c66			sync, vin replacement
Mitsubishi colt	etacs 3140k	ecu 24c04, 24c08.			sync, vin replacement
Mitsubishi ASX	kos 24c16	ecu 93c66			sync, vin replacement
Mitsubishi outlander 3	kos 24c16	oss 93c86	esl 93c56	ecu 93c86 and 25160 and 95320	sync, vin replacement
Mitsubishi i200	immo x24c01	ecu 93c86			sync, vin replacement
Mitsubishi	ecu 8305f, 8304f, 8302f, 8206, 7203fa, 7202.				IMMO OFF
Hyundai, kia.	ecu tricore tc1766,				vin replacement +pin+crc.
santa fe,sorento	ecu EDC17c57				vin replacement, mileage change
sportage, sorento	SMARTRA mc9s12xeg384, mc9s12xeg768.				pin, pin change
Mersedes benz ml320	aam until 2000				repail dump.

Fiat Ducato	immo 93c56	ecu EDC16 95160	restore dump immo and sync.+pin
Fiat Grande Punto	BSI 93c86	ecu 95320, iaw55fh	pin, sync
Fiat Ducato,Iveco Deili, PEUGEOT BOXER3, CITROEN JUMPER3.	BSI Magneti marelli st95640	ecu SID208 ecu EDC17C47-TC1797	<b>sync vin clone BSI CRC</b>
Ssangyong rexton, Kyron, rodius	ecu 95160, 95320.		immo off.
Chrysler	25080		immo off.
ROVER 75	EWS3 0D46J	ecu MEMS3 93c66	sync
	EWS3 0D46J	DDE 95p08	sync
	EWS3 0D46J	ecu EMS2000 29F200	sync
Land Rover Freelander 2	EDC16cp39 95320	CEM 6G9T-14A073-LA 25lc230	SYNC, manual key entry
<b>Range Rover Evouque</b>	EPB, KVM, BCM, ECM.		vin replacement+CRC
<b>BCM2 to ELV for VAG</b>	BCM2 (NEC + 95320) and BCM2 (NEC only)	ELV (908GR16)	data recording: VIN, CS, MAC, power class.
<b>VAG MM7GV</b>	immo dataNEC+24c32	ecu 95320	data recording: VIN, CS, MAC, power class.
	<b>Odo corection ECU</b>		
<b>VAG EGS</b>	VAG AT AISIN 6-speed 95320 VAG AT AISIN 8-speed 95128 VAG AT AISIN 8-speed 95640		mileage change
<b>GAZon NEXT</b>	GAZ Bosch EDC17CV44(54) TC1767		mileage change
<b>VAZ NIVA</b>	Bosch 1797 TC1762		mileage change
<b>KIA HYNDAI</b>	Bosch EDC17C08 TC1766. Bosch EDC17C57 TC1793.		mileage change
<b>VW TOUAREG</b>	Bosch EDC17CP14 TC1796		mileage change
<b>Renault Master3</b>	Bosch EDC17C42 TC1767		mileage change
<b>Opel AstraJ, Corsa D.</b>	Bosch EDC17C19 TC1792 Bosch EDC17C42 TC1767		mileage change
<b>BMW F20</b>	Bosch EDC17C56 TC1797		mileage change

All solutions are made only by hands. They are tested and work on 100%. If you need to quickly repair a car, write me an email, I will try to help you in a short time.

<https://Volvo-fix.com>

immo.frol@gmail.com